

# **Ørsted - East Coast Operational Assets**

**Notice to Mariners** 

Period of Notice: September 2020

**Version: 4** 



## **Table of Contents**

1	Introduction				
	1.1	Subsea Cables	. 4		
	1.2	Wind Farm Positional Data	. 4		
2	Key Co	ontacts	. 5		
3	Notice	to Mariners Summary:	. 6		
4	Race E	Bank – Notice to Mariners	. 7		
	4.1	Lighting and Marking Status	. 7		
	4.2	Other Operations	. 7		
	4.2.1	String 1 cable Replacement	. 7		
	4.2.2	Above water inspections	10		
5	Wester	rmost Rough – Notice to Mariners	10		
	5.1	Lighting and Marking Status	10		
	5.2	Other Operations	10		
	5.2.1	Full Site Bathymetric Survey Westermost Rough	10		
	5.2.2	Above water inspections	11		
6	Lincs -	- Notice to Mariners	12		
	6.1	Lighting and Marking Status	12		
	6.2	Other Operations	12		
	6.2.1	Above water inspections	12		
7	Gunfle	eet Sands – Notice to Mariners	13		
	7.1	Lighting and Marking Status	13		
	7.2	Other Operations	13		
	7.2.1	Transition Piece Maintenance	13		
	7.2.2	Above water inspections	14		
8	Hornse	ea One – Notice to Mariners	15		
	8.1	Lighting and Marking Status	15		
	8.2	Other Operations	15		



8.2.1	Nearshore Export Cable – Potential exposure	15
8.2.2	Structural Inspections Below Water	17
8.2.3	Un-manned Service Vessel (USV) Survey	17
8.2.4	Array cable remedial work	19
8.2.5	Above water inspections	21




#### 1 Introduction

Ørsted is an offshore wind farm owner and operator with ten operational wind farms in UK waters. Of these ten, the following offshore wind farms are located off the East Coast of England:

- Gunfleet Sands
- Westermost Rough
- Race Bank
- Lincs
- Hornsea One

The purpose of this monthly Notice to Mariners (NtM) is to ensure that mariners are aware of any non-routine operations across the East Coast assets that could pose a risk to other sea users. Safety is paramount to Ørsted and this notice should assist in ensuring that both mariners and the Ørsted operational team can operate safely offshore. This NtM will provide:

- A regular, clear and consistent overview of non-routine operations
- Updates relating to lighting and marking
- Key contact details
- Access to detailed site information and figures
- Clarity on when Safety Zones and recommended safe separation distances are in force or requested



- Information relating to routine maintenance carried out by Crew Transfer Vessels (CTV) or Service Operation Vessels (SOV).
- Any information relating to export cables
- Any information relating to offshore wind farms currently in development, construction or not operated by Ørsted

#### **Subsea Cables**

Subsea cables are installed across each offshore wind farm and are marked on the KIS ORCA charts referenced in Section 1.2. Please note the following advice from NP 100 The Mariners Handbook "Every care should be taken to avoid anchoring, trawling, fishing, dredging, drilling, or carrying out any other activity in the vicinity of cables which might damage them." This warning is repeated on all admiralty charts.

#### **Wind Farm Positional Data**





<u>orca.eu/downloads#.XWUTQUxFwjZ.</u> Should mariners require further information or any data in a format that can be used in a plotter or other device, please contact the Company Fisheries Liaison Officer, listed in Section 2 below.

## 2 Key Contacts

For further information on any of the activities listed within this notice, please use the contact details listed below.

Site	Ørsted Mailbox/ Offshore Coordination	Fisheries Industry Representative
Race Bank		Ady Woods
	Phone: 07826 943808	Phone: 07468 898948
	Email: rowoffshorec@orsted.co.uk	Email: firwoods@hotmail.com
Westermost		Guy Pasco
Rough	Phone: 07867 674941	Phone: 07880 362082
	Email: wmroffshorec@orsted.co.uk	Email: guy@seascopefisheries.co.uk
Lincs		Ady Woods
	Phone: 07766443319	Phone: 07468 898948
	Email: lincsoffshorec@orsted.co.uk	Email: firwoods@hotmail.com
Gunfleet	Email. Inicsonshored worsted.co.dk	Merlin Jackson
Sands		Phone: 07989 520484
		Email: merlinjackson@btinternet.com
Hornsea		Nick Garside
One	Phone: 07775005465	Phone: 07538 827013
	Email: HOWoffshoreC@orsted.co.uk	Email: nick.garside@live.co.uk

#### **Company Fisheries Liaison Officer**

The Ørsted Company Fisheries Liaison Officer can be contacted using the details below:

Courtney French

Email: CONFR@Orsted.co.uk



#### 3 **Notice to Mariners Summary:**

Site	Lighting and Marking Status	Survey	Jack-Up Vessel	Other Works
Race Bank	ОК	None	None	String 1 replacement,
Westermost Rough	ОК	Bathymetric Survey	Pacific Orca**	Full site bathymetric survey, Above water Inspections.
Lincs	ОК	None	None	Structural inspection below water, Above water inspections.
Gunfleet Sands	ОК	Bathymetric survey,	Wind Pioneer**	External Painting Campaign°  **, Above water Inspections.
Hornsea One	ОК	None	None	Nearshore export cable Structural inspection below water, USV survey, Array cable remedial*, Met mast dredging°

<sup>\*</sup> Formal 500m safety zone in place

° Licensable activity

\*\* 500m safety distance requested

\*\*\* 200m safety distance requested



#### 4 Race Bank – Notice to Mariners

## 4.1 Lighting and Marking Status

The lighting and/ or navigational warning systems are currently operational. On the 30<sup>th</sup> August once the String 1 cable replacement campaign commences (section 4.2.1) turbines D01 & E01 will not be operational. (Identified on figure 1 below)

#### 4.2 Other Operations

#### 4.2.1 String 1 cable Replacement

The Global Symphony will be completing String 1 cable (see & Figure 2) replacement on Racebank on or around the 20<sup>th</sup> August for approximately 28 days.

Mariners are requested to remain a safe distance of 500m from Global Symphony when it is observed undertaking String 1 replacement.






Figure 1 Race Bank String 1 location




Figure 2 Race Bank String 1 replacement

Table 1 Coordinates of String 1

Point	WGS84 (Decimal Degrees)		WGS84 (Degrees, Minutes, Seconds)		ETRS89 UTM31N	
ID					•	etres)
	Latitude	Longitude	Latitude	Longitude	Easting	Northing
1	53.31915514	0.782630381	53° 19' 08.95324846" N	000° 46' 57.46033658" E	352301	5910067
2	53.32105874	0.806520098	53° 19' 15.80621138" N	000° 48' 23.46331521" E	353899	5910229
3	53.32186137	0.817143875	53° 19' 18.69567434" N	000° 49' 01.70890916" E	354609	5910297
4	53.31676264	0.818859541	53° 19' 00.34024726" N	000° 49' 07.88530871" E	354706	5909726
5	53.31479499	0.795956169	53° 18' 53.25670756" N	000° 47' 45.43317179" E	353174	5909554
6	53.29567808	0.815100403	53° 17' 44.43583086" N	000° 48' 54.35241144" E	354384	5907389
7	53.29248035	0.807259602	53° 17' 32.92402145" N	000° 48' 26.12552908" E	353850	5907049
8	53.30645990	0.793853268	53° 18' 23.25038719" N	000° 47′ 37.86272707" E	353005	5908632



#### **Vessel Details**

	General Information	Vessel Picture
Name	Global Symphony	
Flag	Norway	
Year Built	2011	
IMO Number	232025210	174
Call Sign	MGJH7	
Vessel Contact Details		
Bridge	+4723671810 / +4477324980	
Party Chief	Ross Macdonald	
		Vous
Email	Ross.macdonald@globalmarine.group	James 1

	General Information	Vessel Picture
Name	Rem Inspector	
Flag	Cyprus	
Year Built	2013	180
IMO Number	9662083	
Call Sign	5BUR4	AND SOURCE STATES OF THE PARTY
Vessel Contact Details		without I have been been been been been been been be
Bridge	++45 23 67 88 14 extension 2	
Party Chief	Ross Macdonald	
Email	captain@inspector.remoffshore.no	



#### 4.2.2 Above water inspections

On the 18<sup>th</sup> September we will conduct inspections within the WTG structure, it is expected to last around 30 days dependant on weather.

#### **Vessel Information**

	General Information	Vessel Picture
Name	WEM2	
Flag	British	
Year	2018	
MMSI	232013885	
Call	MCPB7	TOMAN TO THE PARTY OF THE PARTY
	Vessel Contact Details	Web?
Bridge	001 904596 3780 (Sat phone only)	Win
011	Agent: Torben Kuehnel: Email: <u>torben.kuehnel @offshoreservice.de</u>	
Email	wem2 @windenergymarine.com	

## 5 Westermost Rough – Notice to Mariners

## 5.1 Lighting and Marking Status

The lighting and/ or navigational warning systems are currently operational. No planned outages.

#### 5.2 Other Operations

#### 5.2.1 Full Site Bathymetric Survey Westermost Rough

Vessel, the Deep Seapal will be undertaking a full site bathymetric survey of Westermost Rough Windfarm, this will be carried out using a hull mounted multibeam echosounder. This work is due to start on or around the 25th August and the duration will be approximately 14 days. The vessel will have a fishing liaison officer on board for some of the works.



#### **Vessel Information**

	General Information	Vessel Picture
Name	Deep Seapal	
Flag	United Kingdom	110
Year Built	2014	
MMSI Numbe	r235089472	The same of the sa
Call Sign	2 <i>EZU</i> 7	
	Vessel Contact Details	
Bridge	+31(0)6 1322 1213	
Party Chief	Marian Cosma / Fabian van Wijk	DEEP SEAPAL SURVEY
Email	deepseapal@deepbv.nl	

## 5.2.2 Above water inspections

On the 10<sup>nd</sup> September we will conduct inspections within the WTG structure, it is expected to last around 6 days dependant on weather.

	General Information	Vessel Picture
Name	WEM2	
Flag	British	
Year	2018	
MMSI	232013885	
Call	MCPB7	TOTAL
	Vessel Contact Details	wsh2
Bridge	001 904596 3780 (Sat phone only)	William
	Agent: Torben Kuehnel:	
Chief	Email: torben.kuehnel@offshoreservice.de	
Email	wem2 @windenergymarine.com	



## 6 Lincs - Notice to Mariners

## 6.1 Lighting and Marking Status

The lighting and/ or navigational warning systems are currently operational. No planned outages.

## 6.2 Other Operations

#### 6.2.1 Above water inspections

On the 2<sup>nd</sup> September we will conduct inspections within the WTG structure, it is expected to last around 7 days dependant on weather.

	General Information	Vessel Picture
Name	WEM2	
Flag	British	
Year	2018	
MMSI	232013885	
Call	MCPB7	
	Vessel Contact Details	WEN?
Bridge	001 904596 3780 (Sat phone only)	Wan
· · · -	Agent: Torben Kuehnel: Email: <u>torben.kuehnel @offshoreservice.de</u>	The state of the s
Email	wem2 @windenergymarine.com	



#### 7 Gunfleet Sands – Notice to Mariners

## 7.1 Lighting and Marking Status

The lighting and/ or navigational warning systems are currently operational. No planned outages.

#### 7.2 Other Operations

#### 7.2.1 Transition Piece Maintenance.

Transition Piece maintenance will be undertaken on all WTG's on GFS01 + GFS02 from the 11<sup>th</sup> May for a provisional 4 months. Sequence of locations and dates are unavailable as works will be weather dependant and coordinated to ensure no conflict with routine maintenance operations.

We request Mariners observe a safe distance from the affected turbine(s) while works are being carried out.

The CTV's "Discovery and Endeavour" will act as Guard Vessels during the maintenance programme with the vessel broadcasting the Turbine ID, establishment/cancellation of the safety zones and seeking contact with marine traffic approaching or nearing the areas on VHF Channel 16 and 12.

	General Information	Vessel Picture
Name	Discovery	
Flag	British	4
Year Built	2012	
MMSI Number	235096731	
Call Sign	2GEQ9	
Ve	essel Contact Details	
Bridge	07791180629	North Sea Legislav
Party Chief	A Brown + L Devaney	
Email	nsdiscovery@northsealogistics.co.uk	



	General Information	Vessel Picture
Name	Pura vida	
Flag	British	
Year	2009	
MMSI	235087893	
Call Sign	2ESX5	
	Vessel Contact Details	
Bridge	07791180629	North Sea Logistics Pura Vida
Party Chief	R King + J Prytherch	
Email	puravida @northsealogistics.co.uk	

## 7.2.2 Above water inspections

On the 21st October we will conduct inspections within the WTG structure, it is expected to last until December.

	General Information	Vessel Picture
Name	WEM2	
Flag	British	
Year	2018	
MMSI	232013885	
Call	MCPB7	CONTRACTOR OF THE PARTY OF THE
	Vessel Contact Details	wen2
Bridge	001 904596 3780 (Sat phone only)	Wall
	Agent: Torben Kuehnel: Email: <u>torben.kuehnel@offshoreservice.de</u>	
Email	wem2 @windenergymarine.com	



#### 8 Hornsea One – Notice to Mariners

## 8.1 Lighting and Marking Status

The lighting and/ or navigational warning systems are currently operational. No planned outages.

## 8.2 Other Operations

#### 8.2.1 Nearshore Export Cable - Potential exposure.

A potential nearshore Export Cable exposure has been identified (as shown in Figure 3)

Mariners are advised that Hornsea Project are reviewing the geophysical survey data from along the nearshore part of offshore export cable corridor.

Work is planned to re-bury the exposed cable via CFE between the 1<sup>st</sup> September and 10<sup>th</sup> September 2020 by Coastal Challenger. This will be done over 2 passes between these dates.

	General Information	Vessel Picture
Name	Coastal Challenger	
Flag	Dutch	6
Year Built	2012	
IMO/MMSI	9647320 // 244913000	
Call Sign	PBOC	1 24
	Vessel Contact Details	The same of the sa
Bridge	Mob + 31 13 6 05 784	
Party Chief	-	
Email	challenger@coastalworkboats.com	



NADESS
NADESS
NADESS
NADESS
NADESS
NADESS
NADESS

Figure 3 Location of nearshore exposed cable at Hornsea One

Marshchapel

data supplied by Chartworld and produced by Navionics NOT TO BE USED FOR NAVIGATION (See Quotation )

0°6'0"E

The Coordinates of the work site are as follows:

0°3'0"E

53°28'0"N

0° 4,832' E	53° 30,258' N
0° 4,779' E	53° 30,361' N
0° 4,752' E	53° 30,421' N
0° 4,735' E	53° 30,452' N
0° 4,731' E	53° 30,455' N
0° 4,727' E	53° 30,459' N
0° 4,725' E	53° 30,460' N
0° 4,705' E	53° 30,464' N
0° 4,694' E	53° 30,467' N
0° 4,639' E	53° 30,478' N
0° 4,560' E	53° 30,509' N
0° 4,524' E	53° 30,531' N

31,533' N
° 31,425' N
° 31,184' N
° 31,207' N
° 31,601' N
° 31,738' N
° 31,942' N
° 31,952' N
° 31,954' N
° 31,967' N
° 31,983' N
° 31,999' N

Potential Cable Exposure (To be confirmed)

0°12'0"E

Orsted

Survey Zone

0°9'0"E

0° 9,945' E	53° 32,011' N
0° 10,041' E	53° 32,024' N
0° 9,915' E	53° 31,427' N
0° 6,046′ E	53° 30,963′ N
0° 5,998' E	53° 30,957' N
0° 6,120' E	53° 30,862' N
0° 5,580' E	53° 30,538' N
0° 5,130′ E	53° 30,268′ N
0° 4,933' E	53° 30,150′ N
0° 4,883′ E	53° 30,197' N
0° 4,851' E	53° 30,231' N
0° 4,832' E	53° 30,258' N



## 8.2.2 Structural Inspections Below Water

Structural inspections will be taking place on Hornsea 1 windfarm on or around the 14<sup>th</sup> August for approximately 2 days.

Mariners are requested to remain a distance of 500m from HBC Achiever when it is observed undertaking diving work in HOW01, during this period divers will be in the water around the vessel. The proposed end date of this work is 15<sup>th</sup> August

#### **Vessel Information**


	General Information	Vessel Picture
Name	HBC Achiever	
Flag	DENMARK	
Year Built	2014	
MO/MMSI	9647978 / 219305000	
Call Sign	ОWMH2	A Line Paris
	Vessel Contact Details	000
Bridge	+45 28 56 47 99 / +45 28 56 47 99	ate about
Party Chief	Rafal Nierzwicki	Kara Kara
		And the second s
Email	achieverbridge@hbc-tec.dk	

## 8.2.3 Un-manned Service Vessel (USV) Survey

A survey of a USV will take place at HOW01 from the 1st – 4th September. It is operational 24hrs a day. The USV is 4.5m long and driven remotely by a USV pilot. It will be mobilized with GPS, MultiBeam EchoSounder (MBES) and Parametric EchoSounder (PES) for survey, as well as AIS, thermal imaging and light cameras, active radar reflector, and lights, for navigation.



Figure 5



	General Information	Vessel Picture
Name	x 09	
Flag	UK	
Year Built	2020	- 44,
IMO/MMSI	232027632	
Call Sign	MHIJ8	
	Vessel Contact Details	" SIIDVEY
Bridge	Mike Lewis: +353 87 796 4958	Holesconcon 1931 Bustons
Party Chief	Tom Davenport: +44 7759 237 524	
Email	operations@xocean.com	



### 8.2.4 Array cable remedial work

Remedial work will take place on HOW01 String 7 between locations Z13-F03 & F03-E02 shown on figure 1 below. Work is due to commence on 27<sup>th</sup> August 2020 until the end of September 2020.


Mariners must observe an approved safety zone of 500m whenever The Livingstone is next to an OSS or WTG. A minimum separation distance of 500m is also requested when the vessel is observed manoeuvring into position.

	General Information	Vessel Picture
Name	Living Stone	
Flag	Netherlands	7
Year Built	2017	- 11
MO/MMSI Number	IMO 9776925 MMSI 244010952	Approximate the second
Call Sign	PBXN	Photo Control of the
	Vessel Contact Details	
Bridge (Captain)	+49 42151 7219 1983	HVPHO STONE
Party Chief OIM	+49 421 517 219 1982	
Email	Bridge Livingstone@ships deme- group.com	

Į.	General Information	Vessel Picture
Name	Skandi Constructor	
Flag	Bahamas	u ha
Year Built	2009	a was
IMO/MMSI Number	IMO 9431642 MMSI 311 055 900	
Call Sign	C6ZH8	The state of the s
	Vessel Contact Details	
Bridge	+47 23 67 77 30	
Party Chief OIM	+47 23 67 77 30 Extension 219	W
Email	constructor.captain@constructor.dof.no	the same of the same



Figure 6 Hornsea 1 string 7



F03	53° 52' 43.967° N	2° 8' 33.310° E
E02	53° 51' 53.838° N	2° 10' 28.350° E
D01	53° 51' 19.036° N	2° 12' 31.748° E
C01	53° 50' 42.749° N	2° 13' 11.280° E
B01	53° 50' 9.901° N	2° 13' 47.045° E
Z13	0° 06' 09.807° E	53° 52' 38.856° N



## 8.2.5 Above water inspections

On the 21st October we will conduct inspections within the WTG structure, it is expected to last until December.


	General Information	Vessel Picture
Name	WEM2	
Flag	British	
Year	2018	
MMSI	232013885	
Call	MCPB7	The state of the s
	Vessel Contact Details	WEN 2
Bridge	001 904596 3780 (Sat phone only)	Wan
	Agent: Torben Kuehnel: Email: <u>torben.kuehnel @offshoreservice.de</u>	The state of the s
Email	wem2 @windenergymarine.com	



## 8.2.6 Met Mast Dredging

Between the 7<sup>th</sup> to 21<sup>st</sup> September there will be some dredging work taking place around the Met Mast central caisson.

Figure 7



	General Information	Vessel Picture
Name	Skandi Constructor	
Flag	Bahamas	- in a
Year Built	2009	E TOTAL
IMO/MMSI Number	IMO 9431642 MMSI 311 055 900	
Call Sign	C6ZH8	THE RESIDENCE AND ADDRESS OF THE PARTY OF TH
	Vessel Contact Details	The second second
Bridge	+47 23 67 77 30	
Party Chief OIM	+47 23 67 77 30 Extension 219	D.
Email	constructor.captain@constructor.dof.no	The second second