

Ørsted - East Coast Operational Assets

Notice to Mariners

Period of Notice: March 2024

Version: 4



Table of Contents

Τ	Introdu	uction	3
	1.1	Subsea Cables	4
	1.2	Wind Farm Positional Data	4
2	Key Co	ontacts	4
3	Amend	dments from Previous Revision	5
4	Notice	to Mariners Summary:	5
5	Race E	Bank – Notice to Mariners	6
	5.1	Lighting and Marking Status	6
	5.2	Other Operations	6
	5.2.1	Drop down camera survey	6
6	Weste	rmost Rough – Notice to Mariners	7
	6.1	Lighting and Marking Status	7
	6.2	Other Operations	7
7	Lincs -	- Notice to Mariners	7
	7.1	Lighting and Marking Status	7
	7.2	Other Operations	7
	7.2.1	Lincs Generator Exchange	7
	7.2.2	Lincs Gearbox Exchanges	8
	7.3	Cable Exposure	9
8	Gunfle	eet Sands – Notice to Mariners	10
	8.1	Lighting and Marking Status	10
	8.2	Other Operations	10
	8.3	Cable exposure	10
	8.4	MBES Survey	10
		10	
9	Hornse	ea One – Notice to Mariners	11
	9.1	Lighting and Marking Status	
		es situated on the Hornsea Project One / Two adjoining perimeter	
	9.2	Other Operations	13
	9.2.1	COMSY Cable Repair	13
	9.2.2	Blade Repairs and Blade Cowling Bolt retrofits	13



10	Hornse	a Two – Notice to Mariners	15
	10.1	Lighting and Marking Status	15
	10.2	Other Operations	15
	10.2.1	MBES Survey	15
	10.2.2	Major Projects – Turbine Maintenance and Repairs	15

1 Introduction

Ørsted is an offshore wind farm owner and operator with ten operational wind farms in UK waters. Of these ten, the following offshore wind farms are located off the East Coast of England:

- Gunfleet Sands
- Westermost Rough
- Race Bank
- Lincs
- Hornsea One
- Hornsea Two

The purpose of this monthly Notice to Mariners (NtM) is to ensure that mariners are aware of any non-routine operations across the East Coast assets that could pose a risk to other sea users. Safety is paramount to Ørsted and this notice should assist in ensuring that both mariners and the Ørsted operational team can operate safely offshore. This NtM will provide:

- A regular, clear, and consistent overview of non-routine operations
- Updates relating to lighting and marking statuses.
- Key contact details
- Access to detailed site information and figures
- Clarity on when Safety Zones and recommended safe separation distances are in force or requested.



This Notice to Mariners will not provide:

- Information relating to routine maintenance carried out by Crew Transfer Vessels (CTV) or Service Operation Vessels (SOV).
- Any information relating to export cables.



 Any information relating to offshore wind farms currently in development, construction or not operated by Ørsted.

Subsea Cables

Subsea cables are installed across each offshore wind farm and are marked on the KIS ORCA charts referenced in Section 1.2. Please note the following advice from NP 100 The Mariners Handbook "Every care should be taken to avoid anchoring, trawling, fishing, dredging, drilling, or carrying out any other activity in the vicinity of cables which might damage them." This warning is repeated on all admiralty charts.

Wind Farm Positional Data

KIS ORCA Awareness Charts (including the layout and coordinates) and Fishing Plotter Files of the offshore assets referenced in this NtM can be found via the KIS ORCA website: https://kis-orca.org/downloads/ Should mariners require further information or any data in a format that can be used in a plotter or other device, please contact the Company Fisheries Liaison Officer, listed in Section 2 below.

2 Key Contacts

For further information on any of the activities listed within this notice, please use the contact details listed below.

Site	Ørsted Mailbox/ Offshore Coordination	Fisheries Industry Representative
Race Bank	Phone: 07826 943808 Email: rowoffshorec@orsted.com	Ady Woods Phone: 07468 898948 Email: firwoods@hotmail.com
Westermost Rough	Phone: 07867 674941 Email: <u>wmroffshorec@orsted.com</u>	Guy Pasco Phone: 07880 362082 Email: guy@seascopefisheries.co.uk
Lincs	Phone: 07766443319	Ady Woods Phone: 07468 898948 Email: firwoods@hotmail.com
Gunfleet Sands	Email: <u>lincsoffshorec@orsted.com</u>	Merlin Jackson Phone: 07989 520484 Email: merlinjackson@btinternet.com
Hornsea One	Phone: 07775005465 Email: HOWoffshoreC@orsted.com	Nick Garside Phone: 07538 827013 Email: nick.garside@live.co.uk
Hornsea Two	Phone: 07775005465 Email: HOW02offshoreC@orsted.com	Nick Garside Phone: 07538 827013 Email: nick.garside@live.co.uk

Company Fisheries Liaison Officer

The Ørsted Company Fisheries Liaison Officer can be contacted using the details below:

Lee Thompson

Email: <u>LEETH@orstred.com</u>

Callum Vale



Email: <u>CAVAL@orstred.com</u>

3 **Amendments from Previous Revision**

Added/Removed	Description
9.2.1	Added COMSY cable repair
9.2.2	Blade Repairs and Blade Cowling Bolt Retrofits
10.2.2	Major Project – Turbine Maintenance and Repairs
5.2.2	Removed Wave Buoy removal

Notice to Mariners Summary: 4

Site	Lighting and Marking Status	Survey	Jack-Up Vessel	Other Works
Race Bank	OK	Yes	None	Drop Down Camera Survey.
Westermost Rough	OK	None	None	None Currently.
Lincs	OK	None	Yes	Generator Exchange°* Gearbox Exchange°*
Gunfleet Sands	OK	None	None	None currently.
Hornsea One	PO1 –Marine Lanterns Extinguished Fog signal inoperable	None	None	COMSY Cable Repair ****
Hornsea Two	OK	Yes	None	MBES Survey Major Project Turbine Maintenance and Repairo*

^{*} Formal 500m safety zone in place

Status of lighting & marking is correct at time of issue; any changes will be communicated through an updated version being issued.

[°] Licensable activity

^{** 500}m safety distance requested *** 100m safety distance requested

^{**** 250}m safety distance requested



5 Race Bank – Notice to Mariners

5.1 Lighting and Marking Status

The lighting and/ or navigational warning systems are currently operational. No planned outages

5.2 Other Operations

5.2.1 Drop down camera survey.


Start date: Approximately March 2024 Duration of work scope: Approx 5 days

Description of work: Drop down camera (DDC) survey a various locations shown below.

Is this a licensed activity: Yes

Safety zone required: No, however survey work will include underwater photography at multiple locations (detailed below). Mariners are requested to remain a distance of 250m from "Isla B" when it is observed undertaking this survey work due to the survey equipment that will be in the water. The equipment will be lowered using a frame winch on the aft of the vessel.

	General Information	Vessel Picture
Name	Isla B	
Flag	United Kingdom (GB)	
Year Built	1961	
MMSI Number	232007860	and the
Call Sign	MNVM2	
	Vessel Contact Details	W WHITE A
Bridae	+44 (0) 7969559716	TR.110
Party Chief	Gary Robinson	Harris EB.Mo
Email	Gary.robinson@ocean-ecology.com	3 Sean Boyce





6 Westermost Rough – Notice to Mariners

6.1 Lighting and Marking Status

The lighting and/ or navigational warning systems are currently operational. No planned outages

6.2 Other Operations

N/A

7 Lincs – Notice to Mariners

7.1 Lighting and Marking Status

The lighting and/ or navigational warning systems are currently operational. No planned outages.

7.2 Other Operations

7.2.1 Lincs Generator Exchange

Start date: 18th March 2024.

Duration of work: 26 days (depending on weather)

Description of work: Exchange of generator at five WTG locations (LS18 = E18, LS53=D53, LS44 = B44, LS55 = D55 and LS51 = A51) using a Jack Up Vessel that will be lifted above the sea level and including use of a large crane.

Is this a licensed activity: Yes - covered by existing marine licence.


WTG	Degrees, Decimal Mi	nutes
ID	Latitude	Longitude
LS18	53° 13′ 30.637″ N	000° 28' 50.385" E
LS53	53° 14′ 30.620″ N	000° 30' 08.933" E
LS44	53° 11' 00.963" N	000° 30' 13.527" E
LS55	53° 13′ 50.224″ N	000° 30' 25.959" E
LS51	53° 08' 21.877" N	000° 30′ 10.969″ E

Safety zone required: Mariners must observe an approved safety zone of 500m whenever J/U Wind is attached to a WTG. A minimum separation distance of 500m is also requested when the vessel is observed manoeuvring into position.

Vessel Information

	General Information	Vessel Picture
Name	I/U WIND	
Flag	Denmark	
Year Built	1996	
MMSI Number	220520000	
Call Sign	MO 9107851	
	Vessel Contact Details	to the
Bridge	+4520485586	
Party Chief	none	
Email	<u>Master.wind@ziton.eu</u>	





ENTRY ROUTES TO FARM

7.2.2 Lincs Gearbox Exchanges

Start date: 18th March 2024

Duration of work: 20 days (depending on weather)

Description of work: Exchange of gearboxes at three WTG locations (LS71 = F71, LS02 = E02 and LS46 = B46) and main bearing exchange at LS29 = H29 using a Jack Up Vessel that will be lifted above the sea level and including use of a large crane.

Is this a licensed activity: Yes - covered by existing marine licence.

Safety zone required: Mariners must observe an approved safety zone of 500m whenever GMS Endeavour is attached to a WTG. A minimum separation distance of 500m is also requested when the vessel is observed manoeuvring into position.


Vessel Information

	General I	nformatio	on	Vessel Picture
Name	GMS Endea	vour		
Flag	Panama	WTG	Degrees, Decim	\ f .
Year Built	2011	ID		
MMSI Number	r370582000	/ IMO 95	58983 Latitude	
Call Sign	3EUG6	LS71	53° 12' 29.282"	
	Vessel Co		.53° 14' 07.402"	
Bridge	+44 2922 4	1546 12026	53° 09' 03.994"	
Master	None	LSZY	33 07 03.774	
Email	Endeavour.ı	master@f	leet.gmsplc.com	



7.3 Cable Exposure

We have been made aware some exposed array cables at four locations on Lincs windfarm.



Corner	WTG	Name	FTR S89 LITM	31N (metres)	WGS84 (Deci	mal Degrees)	WGS84 (Degrees,	decimal Minutes)	WGS84 (Deg	Min, Seconds)		Length of	
Point	ID	Plate	LINGS OTH	` ′	,	,	, , ,	•	, ,		Point		Comment
ID	10	ID	Easting	Northing	Longitude	Latitude	Longitude	Latitude	Longitude	Latitude	ID	cable	
Α			333273.91	5902136.34	0.501419468	53.242287447	0° 30,085' E	53° 14,537' N	0° 30' 05,110" E	53° 14' 32,235" N	Α		Within
В	D53	LS53	333391.21	5902136.34	0.503175518	53.242324262	0° 30,191' E	53° 14,539' N	0° 30' 11,432" E	53° 14' 32,367" N	В	87	54m of
C	D55	L333	333391.21	5902028.04	0.503232160	53.241351645	0° 30,194' E	53° 14,481' N	0° 30' 11,636" E	53° 14' 28,866" N	С	07	WTG
D			333273.91	5902028.04	0.501476149	53.241314832	0° 30,089' E	53° 14,479' N	0° 30' 05,314" E	53° 14' 28,733" N	D		WIG
E			331800.12	5900295.27	0.480327896	53.225289161	0° 28,820' E	53° 13,517' N	0° 28' 49,180" E	53° 13' 31,041" N	E		Within
F	E18	LS18	331833.45	5900295.27	0.480826590	53.225299709	0° 28,850' E	53° 13,518' N	0° 28' 50,976" E	53° 13' 31,079" N	F	6	20m of
G	C10	L310	331833.45	5900265.86	0.480842097	53.225035642	0° 28,851' E	53° 13,502' N	0° 28' 51,032" E	53° 13' 30,128" N	G	0	WTG
Н			331800.12	5900265.86	0.480343406	53.225025094	0° 28,821' E	53° 13,502' N	0° 28' 49,236" E	53° 13' 30,090" N	Н		WIG
J			330316.15	5898483.91	0.459084676	53.208550947	0° 27,545' E	53° 12,513' N	0° 27' 32,705" E	53° 12' 30,783" N	J		Within
K	F71	LS71	330411.61	5898483.91	0.460512633	53.208581405	0° 27,631' E	53° 12,515' N	0° 27' 37,845" E	53° 12' 30,893" N	K	86	63m of
L	F/I	LS/I	330411.61	5898401.38	0.460556480	53.207840247	0° 27,633' E	53° 12,470' N	0° 27' 38,003" E	53° 12' 28,225" N	L	00	WTG
M			330316.15	5898401.38	0.459128547	53.207809791	0° 27,548' E	53° 12,469' N	0° 27' 32,863" E	53° 12' 28,115" N	M		WIG



8 Gunfleet Sands – Notice to Mariners

8.1 Lighting and Marking Status

The lighting and/ or navigational warning systems are currently operational. No planned outages.

8.2 Other Operations

No current other operations.

8.3 Cable exposure

There are subsea cables currently exposed as shown on the below coordinates.

		WGS	84 Degrees, decimal Mi	nutes		
ID	ArrayCableID	Length_m	StartCoord_Longitude	StartCoord_Latitude	EndCoord_Longitude	EndCoord_Latitude
GFS_MBES_T0_01-UnidentifiedOther	F08-F09	13.4	1° 17.383' E	51° 44.721' N	1° 17.396' E	51° 44.723′ N
GFS_MBES_T0_02-CableExposure	F08-F09	790.93	1° 16.787' E	51° 44.486′ N	1° 17.376' E	51° 44.718' N
GFS_MBES_T0_03-CableExposure	F07-F08	533.19	1° 16.562' E	51° 44.401′ N	1° 16.726' E	51° 44.466′ N
GFS_MBES_T0_04-CableExposure	F06-F07	25.25	1° 16.059' E	51° 44.203′ N	1° 16.075' E	51° 44.210′ N

8.4 MBES Survey

East Coast Hub Notice to Mariner (NtM) Requirement

This information needs to be provided a minimum of 14 days prior to the project start date.

Start date: Start February Duration of work scope: 1 day

Description of work: MBES survey in a 300x300m box around 6 turbines

Is this a licensed activity: Yes/No No

Safety zone required. If Yes what distance? None

Vessel Information

	General Information	Vessel Picture
Name	Spectrum 1	4+
Flag	UK	/ -
Year Built	2009	
MMSI Number	235075021	
Call Sign	2CQX3	
	Vessel Contact Details	
Bridge	+44 (0) 7538565561	CONTRACTOR OF THE PARTY OF THE
Party Chief	TBD	Section 1
Email	spectrum1@spectrum-offshore.com	

WTG ID	Degrees, Decimal Minutes	
	Latitude	Longitude
B01	51°43.517'N	01°11.464'E
B03	51°44.029'N	01°12.776'E
B06	51°44.797'N	01°14.744'E
C06	51°44.590'N	01°14.923'E
G02	51°42.738'N	01°13.015'E
F00	51°42.434'N	01°11.524'E



9 Hornsea One – Notice to Mariners

9.1 Lighting and Marking Status

PO1 Yellow Marine Lanterns Extinguished and Fog Horns Inoperable.


Turbines situated on the Hornsea Project One / Two adjoining perimeter

Mariners are advised that the marine navigation lighting and foghorns on turbines situated on the Hornsea Project One / Two adjoining perimeter have now been extinguished. Marine navigation lighting will now alight the combined perimeter of Hornsea Project One and Two.

Please see the table below showing the locations where the foghorns/marine navigation lighting has been discontinued (indicated with an X)

Turbine	Marine Navigation Lights	Foghorns
K25	X	
Q20	X	Х
C30	X	Х
H27	X	Х
P22	X	Х
L20		Х
K16		Х
K10		Х
M05		Х

Orsted





9.2 Other Operations

9.2.1 COMSY Cable Repair

Start Date: 19/03/2024.

Duration of work scope: 1 week

Description of work scope: COMSY cable repair


Is this a licensed activity: No

Safety zone required: Mariners are requested to remain at a distance of 250m from the locations

below while the Channel Chieftain or work party are carrying out works.

General Information		Vessel Picture
Name	CHANNEL CHIEFTAIN IX	
Flag	UK	· ·
Year Built	2017	
MMSI Numbe	er 232005600	The state of the s
Call Sign	MAKS5	ALV-VELLE STATE
	Vessel Contact Details	
Bridge		
Party Chief		
Email	cc9@carlinboatcharters.com	

Coordinates example



WTG ID	Degrees, Decimal Minutes	
	Latitude	Longitude
A23	53°50' 11.48'N	01°49' 42.519'E
E21	53°52' 10.815'N	01°49' 42.004'E
J10	53°54' 40.460'N	01°58' 57.842'E

9.2.2 Blade Repairs and Blade Cowling Bolt retrofits

Start Date: 24/04/2024.

Duration of work scope: 24th April – 31st November

Description of work scope: Major Projects – Turbine Maintenance and Repairs

Is this a licensed activity: YES

Safety zone required: Mariners are requested to remain at a distance of 250m from the locations

where external rope works are witnessed


General Information		
Name	Njord Thor	
Flag	Jersey	
Year Built	2015	
MMSI Numbe	er 235108495	
Call Sign	2ICE2	
	Vessel Contact Details	
Bridge	+447496675260	
Party Chief		
Email	njordthor@njordoffshore.com	



General Information		
Name	HST Sofia	
Flag	UK	
Year Built	2019	
MMSI Numbe	er232020271	
Call Sign	MEPI4	
	Vessel Contact Details	
Bridge	+44 73 8738 3158	
Party Chief		
Email	hstsofia@purus.com	



Coordinates example



WTG ID	Degrees, Decimal Minutes	
(For Blade Repairs)	Latitude	Longitude
A19	53°50'5.340"N	01°54'34.121"E
A23	53°50'11.478"N	01°49'42.519"E
A24	53°50'10.027"N	01°48'16.430"E
B16	53°50'42.731"N	01°58'20.716"E
B22	53°50'50.737"N	01°50'7.208"E
B23	53°50'49.291"N	01°48'27.938"E
C18	53°51'48.777"N	01°55'0.387"E
C20	53°51'28.596"N	01°52'31.220"E
F13	53°52'32.023"N	01°58'49.544"E
F21	53°52'57.834"N	01°48'50.122"E
G07	53°53'17.692"N	02°2'58.029"E
H07	53°53'58.250"N	02°2'13.562"E
H20	53°54'32.240"N	01°49'8.214"E
J07	53°54'32.071"N	02°1'36.460"E
K03	53°55'19.794"N	02°5'42.840"E
K18	53°55'17.753"N	01°50'48.118"E



10 Hornsea Two – Notice to Mariners

10.1 Lighting and Marking Status

The lighting and/ or navigational warning systems are currently operational. No planned outages.

10.2 Other Operations

10.2.1 MBES Survey

Start Date: Mid-December

Duration of works scope: 1 Month.

Description of work: Full site MBES survey incl. EC's to KP. 7

Is this a licensed activity: Yes/No

Safety zone required. If Yes what distance? No

Vessel Information

	General Information	Vessel Picture
Name	Deep Breaker	
Flag	Panam a	. 1
Year Built	1956	
MMSI	371150000	
Call Sign	HP4641	The second second
	Vessel Contact Details	1000000
Bridge	GSM: +31615367813 SAT: +31208085042	SURVEY
Party Chief	TBD	
Email	breakers urvey57@gmail.com	William to make

10.2.2 Major Projects - Turbine Maintenance and Repairs

Start Date: 24/04/2024.


Duration of work scope: 24th April – 31st November

Description of work scope: Major Projects – Turbine Maintenance and Repairs

Is this a licensed activity: YES

Safety zone required: Mariners must observe an approved safety zone of 500m whenever Esvagt Froude is attached to a WTG. A minimum separation distance of 500m is also requested when the vessel is observed manoeuvring into position.

General Information		Vessel Picture
Name	Esvagt Froude	
Flag	Denmark	
Year Built	2015	The state of the s
MMSI Numbe	er 219590000	
Call Sign	OWWN2	
	Vessel Contact Details	- ESVAGT
Bridge	/P Phone +45 82 136 216	
Party Chief		
Email	froude@esvagtvessel.com	VersylFinder



WTG ID's

107 pos: A34, A35, A37, A38, A40, A41, B33, B34, B35, B37, B38, B39, B40, C31, C33, C34, C35, C36, C37, C38, C40, D31, D34, D36, E30, E35, E37, E39, F30, F31, F34, F36, F38, G28, G31, G33, G36, H28, H31, H34, J28, J30, J33, J34, J35, J36, J37, K27, K28, K35, K36, L07, L28, L30, L33, L36, M07, M10, M13, M16, M18, M23, M25, M28, M30, M31, M33, M34, M35, N05, N13, N16, N23, N24, N33, N34, N35, P03, P07, P10, P18, P29, P30, P31, P34, Q01, Q05, Q07, Q13, Q21, Q25, Q31, Q34, R20, R22, R23, S03, S04, S05, S12, S15, S33, T17, T18, T20, T21,T22