

Triton Knoll Offshore Wind Farm

Local Notice to Mariners

Issuer: Triton Knoll Marine Coordination Centre

Date of Issue: 28/09/2020

NTM: TK – 18:2020

For general enquiries please contact via email:

tkmcc@smchse.com
l.cornwell@tritonknoll.co.uk
info@tritonknoll.co.uk

For fisheries enquiries please contact via email:

d.proctor@precisionmarine.co.uk



Mariners are advised that the following demarcation buoys outlining the Triton Knoll construction site have moved location as outlined below

TK10 Special mark – has moved south approx. 150 metres from original location.

TK12 East Cardinal – has moved south approx. 100metres from the original location.

Buoy Type	Designation	Characteristics	New position
Special Mark	TK10	Fl.Y.5s	53°29'.51N 000°55'.31E
East Cardinal	TK12	Q(3) 10s	53°24'.31N 001°00'.23E



Figure 1: Example deployed Cardinal, Special Mark and Metecean Buoys

Original charted locations are stated below Notice to Mariners 6175 (P)/2019 England East Coast – Works. Windfarm.
Buoyage. Restricted Area

ADMIRALTY NOTICES TO MARINERS

6175(P)/2019 ENGLAND - East Coast - Works. Wind farm. Buoyage. Restricted area.

Source: Partrac

(SEP: 2019000262416 - 199806).

1. Work is about to commence on the construction of the Triton Knoll Offshore Wind Farm. The site boundary will be marked by light-buoys as follows:

<i>Buoy Type</i>	<i>Designation</i>	<i>Characteristic</i>	<i>Position</i>
South Cardinal	TK01	Q(6)+LFl.15s	53° 24'·05N., 0° 57'·93E.
Special Mark	TK02	FLY.5s	53° 24'·57N., 0° 54'·43E.
Special Mark	TK03	FLY.5s	53° 26'·13N., 0° 50'·01E.
Special Mark	TK04	FLY.5s	53° 27'·46N., 0° 45'·93E.
South Cardinal	TK05	VQ(6)+LFl.10s	53° 28'·86N., 0° 41'·18E.
Special Mark	TK06	FLY.5s	53° 30'·81N., 0° 41'·83E.
North Cardinal	TK07	Q	53° 32'·20N., 0° 44'·25E.
Special Mark	TK08	FLY.5s	53° 32'·44N., 0° 47'·68E.
North Cardinal	TK09	VQ	53° 32'·43N., 0° 52'·04E.
Special Mark	TK10	FLY.5s	53° 29'·60N., 0° 55'·31E.
Special Mark	TK11	FLY.5s	53° 26'·98N., 0° 57'·97E.
East Cardinal	TK12	Q(3)10s	53° 24'·37N., 1° 00'·23E.

2. Metocean buoys will be deployed in the following positions:

53° 26'·00N., 0° 55'·09E.

53° 30'·58N., 0° 47'·94E.

3. A safety zone of 500 metres becomes operational around the turbines under construction.
4. All vessels should navigate with caution in the area.
5. These changes will be included in the next New Editions of Charts 107, 1190 and 1503. (ETRS89 DATUM)

Charts affected - 107 - 1190 (INT 1508) - 1503 (INT 1509)

*****Note*****

Mariners are advised to avoid entering these areas at all times.

For up to date information please contact Guard Vessel Sorrento VHF Ch16 & VHF Ch10.

Triton Knoll Marine Coordination Centre can be contacted by phone or Email on the below details for further information.

*****PLEASE SHARE ACCORDINGLY*****

Triton Knoll Marine Coordination Centre Contact Details:

M: 07384 807 528

T: 0045 82 13 62 19

@: tkmcc@smchse.com