

Ørsted - East Coast Operational Assets

Notice to Mariners

Period of Notice: February 2022

Version: Issue 1



Table of Contents

1	Introdu	ction	3		
	1.1	Subsea Cables	3		
	1.2	Wind Farm Positional Data	3		
2	Key Co	ontacts	4		
3	Notice	to Mariners Summary:	5		
4	Race Bank – Notice to Mariners				
	4.1	Lighting and Marking Status	6		
	4.2	Other Operations	6		
5	Westermost Rough – Notice to Mariners				
	5.1	Lighting and Marking Status	6		
	5.2	Other Operations	6		
6	Lincs -	- Notice to Mariners	6		
	6.1	Lighting and Marking Status	6		
	6.2	Other Operations	6		
7	Gunfleet Sands – Notice to Mariners				
	7.1	Lighting and Marking Status	7		
	7.2	Other Operations	7		
	7.2.1	Above water inspections	7		
	7.3	Cable exposure	8		
8	Hornsea One – Notice to Mariners				
	8.1	Lighting and Marking Status	8		
	8.2	Other Operations	8		



1 Introduction

Ørsted is an offshore wind farm owner and operator with ten operational wind farms in UK waters. Of these ten, the following offshore wind farms are located off the East Coast of England:

- Gunfleet Sands
- Westermost Rough
- Race Bank
- Lincs
- Hornsea One

The purpose of this monthly Notice to Mariners (NtM) is to ensure that mariners are aware of any non-routine operations across the East Coast assets that could pose a risk to other sea users. Safety is paramount to Ørsted and this notice should assist in ensuring that both mariners and the Ørsted operational team can operate safely offshore. This NtM will provide:

- A regular, clear and consistent overview of non-routine operations
- Updates relating to lighting and marking
- Key contact details
- Access to detailed site information and figures
- Clarity on when Safety Zones and recommended safe separation distances are in force or requested



- Information relating to routine maintenance carried out by Crew Transfer Vessels (CTV) or Service Operation Vessels (SOV).
- Any information relating to export cables
- Any information relating to offshore wind farms currently in development, construction or not operated by Ørsted

Subsea Cables

Subsea cables are installed across each offshore wind farm and are marked on the KIS ORCA charts referenced in Section 1.2. Please note the following advice from NP 100 The Mariners Handbook "Every care should be taken to avoid anchoring, trawling, fishing, dredging, drilling, or carrying out any other activity in the vicinity of cables which might damage them." This warning is repeated on all admiralty charts.

Wind Farm Positional Data

KIS ORCA Awareness Charts (including the layout and coordinates) and Fishing Plotter Files of the offshore assets referenced in this NtM can be found via the KIS ORCA website: https://kis-





<u>orca.org/downloads/</u> Should mariners require further information or any data in a format that can be used in a plotter or other device, please contact the Company Fisheries Liaison Officer, listed in Section 2 below.

2 Key Contacts

For further information on any of the activities listed within this notice, please use the contact details listed below.

Site	Ørsted Mailbox/ Offshore Coordination	Fisheries Industry Representative
Race Bank	Phone: 07826 943808 Email: rowoffshorec@orsted.co.uk	Ady Woods Phone: 07468 898948 Email: firwoods@hotmail.com
Westermost Rough	Phone: 07867 674941 Email: wmroffshorec@orsted.co.uk	Guy Pasco Phone: 07880 362082 Email: guy@seascopefisheries.co.uk
Lincs Gunfleet Sands	Phone: 07766443319 Email: lincsoffshorec@orsted.co.uk	Ady Woods Phone: 07468 898948 Email: firwoods@hotmail.com Merlin Jackson Phone: 07989 520484 Email: merlinjackson@btinternet.com
Hornsea One	Phone: 07775005465 Email: <u>HOWoffshoreC@orsted.co.uk</u>	Nick Garside Phone: 07538 827013 Email: nick.garside@live.co.uk

Company Fisheries Liaison Officer

The Ørsted Company Fisheries Liaison Officer can be contacted using the details below:

Courtney French

Email: CONFR@Orsted.co.uk



3 **Notice to Mariners Summary:**

Site	Lighting and Marking Status	Survey	Jack-Up Vessel	Other Works
Race Bank	ОК	None	None	None
Westermost Rough	ОК	None	None	None
Lincs	OK	None	None	None
Gunfleet Sands	ОК	None	None	Above water inspections
Hornsea One	H27 Fog Signal	None	None	None

^{*} Formal 500m safety zone in place

Status of lighting & marking is correct at time of issue; any changes will be communicated through an updated version being issued.

[°] Licensable activity
** 500m safety distance requested

^{*** 200}m safety distance requested



4 Race Bank – Notice to Mariners

4.1 Lighting and Marking Status

L07 currently has temporary marine lanterns installed. No further planned outages.

4.2 Other Operations

Non planned

5 Westermost Rough – Notice to Mariners

5.1 Lighting and Marking Status

The lighting and/ or navigational warning systems are currently operational. No planned outages.

5.2 Other Operations

Non planned

6 Lincs – Notice to Mariners

6.1 Lighting and Marking Status

The lighting and/ or navigational warning systems are currently operational. No planned outages.

6.2 Other Operations

Non planned



7 Gunfleet Sands – Notice to Mariners

7.1 Lighting and Marking Status

The lighting and/ or navigational warning systems are currently operational. No planned outages.

7.2 Other Operations

7.2.1 Above water inspections

On the 9th Feb we will commence an inspection campaign with the vessel Commander P. We anticipate the campaign taking 48 days.

Vessel information

	General Information	Vessel Picture			
Name	Commander P				
Flag	UK				
Year Built					
IMO/MMSI	235097748				
Call Sign	2GIU6				
Vessel Contact Details		DOMESTIC TON			
Bridge	+45 30 53 62 33	OFFICE COMMERCES (
Party Chief	+ 447668 23277	TO BE			
		AND			
Email	mike@offshoreturbineservices.co.uk				




7.3 Cable exposure

There are subsea cables currently exposed as shown on the below chart and coordinates.

Array cable	Nearest WTG	Distance from WTG to start exposure [m]	Exposure length [m]	Coordinates start exposure		Coordinates end exposure	
				x	Υ	x	Y
F06-F07	F07	53.9	73.9	380400.9	5733188.0	380341.2	5733147.0
F07-F08	F08	52.4	216.1	381166.3	5733649.0	380982.7	5733538.0
F08-F09	F08	28.1	827.9	381238.4	5733685.0	381942.3	5734108.0
G03-G04	G03	19.9	129.8	377595.9	5731011.0	377708.3	5731074.0
G07-G08	G07	15.4	5.8	380657.0	5732835.0	380662.0	5732838.0
G07-G08	G08	6.5	11.0	381404.9	5733280.0	381395.3	5733275.0

Table 5-1; Array cable exposures detected in GFS0102



8 Hornsea One – Notice to Mariners

8.1 Lighting and Marking Status

H27 Foghorn is currently inoperative.

8.2 Other Operations

Non planned