

Ørsted - East Coast Operational Assets

Notice to Mariners

Period of Notice: September 2022

Version: 1



Table of Contents

1	Introduction				
	1.1	Subsea Cables	3		
	1.2	Wind Farm Positional Data	4		
2	Key Co	ontacts	5		
3	Notice	to Mariners Summary:	6		
4	Race E	Bank – Notice to Mariners	7		
	4.1	Lighting and Marking Status	7		
	4.2	Other Operations	7		
	4.2.1	Benthic Survey	7		
	4.2.2	SIAW	8		
5	Wester	rmost Rough – Notice to Mariners	9		
	5.1	Lighting and Marking Status	9		
	5.2	Other Operations	9		
	5.1.1	Blade LEP campaign	9		
	5.1.2	Below water Inspections	0		
6	Lincs -	- Notice to Mariners 1	1		
	6.1	Lighting and Marking Status1	1		
	6.2	Other Operations	1		
	6.2.1	LS62 Generator Replacement	1		
7	Gunfle	et Sands – Notice to Mariners1	3		
	7.1	Lighting and Marking Status1	3		
	7.2	Other Operations	3		
	7.3	Cable exposure1	3		
8	Hornse	ea One – Notice to Mariners	4		
	8.1	Lighting and Marking Status1	4		
	8.2	Other Operations	4		
	8.2.1	Drone Blade Inspections	4		



Introduction 1

Ørsted is an offshore wind farm owner and operator with ten operational wind farms in UK waters. Of these ten, the following offshore wind farms are located off the East Coast of England:

- **Gunfleet Sands**
- Westermost Rough
- Race Bank
- Lincs
- Hornsea One

The purpose of this monthly Notice to Mariners (NtM) is to ensure that mariners are aware of any non-routine operations across the East Coast assets that could pose a risk to other sea users. Safety is paramount to Ørsted and this notice should assist in ensuring that both mariners and the Ørsted operational team can operate safely offshore. This NtM will provide:

- A regular, clear and consistent overview of non-routine operations
- · Updates relating to lighting and marking
- Key contact details
- Access to detailed site information and figures
- Clarity on when Safety Zones and

recommended safe separation distances are in force or requested

This Notice to Mariners will not provide:

- Information relating to routine maintenance carried out by Crew Transfer Vessels (CTV) or Service Operation Vessels (SOV).
- Any information relating to export cables
- Any information relating to offshore wind farms currently in development, construction or not operated by Ørsted

Subsea Cables

Subsea cables are installed across each offshore wind farm and are marked on the KIS ORCA charts referenced in Section 1.2. Please note the following advice from NP 100 The Mariners Handbook "Every care





should be taken to avoid anchoring, trawling, fishing, dredging, drilling, or carrying out any other activity in the vicinity of cables which might damage them." This warning is repeated on all admiralty charts.

Wind Farm Positional Data

KIS ORCA Awareness Charts (including the layout and coordinates) and Fishing Plotter Files of the offshore assets referenced in this NtM can be found via the KIS ORCA website: https://kis-orca.org/downloads/ Should mariners require further information or any data in a format that can be used in a plotter or other device, please contact the Company Fisheries Liaison Officer, listed in Section 2 below.



2 Key Contacts

For further information on any of the activities listed within this notice, please use the contact details listed below.

Site	Ørsted Mailbox/ Offshore Coordination	Fisheries Industry Representative
Race Bank	Phone: 07826 943808 Email: rowoffshorec@orsted.com	Ady Woods Phone: 07468 898948 Email: firwoods@hotmail.com
Westermost Rough	Phone: 07867 674941 Email: wmroffshorec@orsted.com	Guy Pasco Phone: 07880 362082 Email: guy@seascopefisheries.co.uk
Cunfleet Sands	Phone: 07766443319 Email: lincsoffshorec@orsted.com	Ady Woods Phone: 07468 898948 Email: firwoods@hotmail.com Merlin Jackson Phone: 07989 520484 Email: merlinjackson@btinternet.com
Hornsea One	Phone: 07775005465 Email: HOWoffshoreC@orsted.com	Nick Garside Phone: 07538 827013 Email: nick.garside@live.co.uk

Company Fisheries Liaison Officer

The Ørsted Company Fisheries Liaison Officer can be contacted using the details below:

Courtney French

Email: CONFR@Orsted.com



3 **Notice to Mariners Summary:**

Site	Lighting and Marking Status	Survey	Jack-Up Vessel	Other Works
Race Bank	ОК	Yes	None	Blade campaign
Westermost Rough	ОК	Yes	Yes	Blade LEP, Below water Inspections
Lincs	OK – Fog signals	None	Yes	Main Generator Replacement*
Gunfleet Sands	ОК	None	None	None
Hornsea One	A04 marine lantern & fog signal.	None	None	None

^{*} Formal 500m safety zone in place

Status of lighting & marking is correct at time of issue; any changes will be communicated through an updated version being issued.

[°] Licensable activity

^{** 500}m safety distance requested
*** 200m safety distance requested
**** 250m safety distance requested



4 Race Bank – Notice to Mariners

4.1 Lighting and Marking Status

The lighting and/ or navigational warning systems are currently operational. No planned outages.

4.2 Other Operations

4.2.1 Benthic Survey

The survey vessel Seren Las benthic survey still to be done, expecting throughout September. See below for locations.

Vessel Information

	General Information	Vessel Picture		
Name	Seren Las			
Flag	United Kingdom [GB]	THE PROPERTY OF THE PROPERTY O		
Year Built				
MMSI	235087047			
Call Sign	MDAH2	SURVEY		
	Vessel Contact Details	SEPENIAS		
Bridge		To the second se		
Party Chief		The state of the s		
Email				


WTG ID	Latitude	Longitude
A03	53 19 166N	00 46 392E
D06	53 18 087N	00 48 770E
E08	53 15 403N	00 48 960E
F05	53 15 548N	00 49 941E
G03	53 16 315N	00 50 659E
H06	53 14 550N	00 51 267E
J01	53 16 852N	00 52 107E
J03	53 15 876N	00 52 130E
Export Cable Route	See Below note	See Below note

Notes:

Text from the methodology: At each of these, a cruciform of grab stations have been arranged with four grab stations at 150 m from the turbine on the cardinal points aligned to the dominant tidal flow and two further grab stations at 300 m distance aligned to the tidal flow.



They will also be sampling outside of the array in the areas shown below and at locations along the export cable route.



4.2.2 SIAW

The Blue Norther will be arriving on site early September 2022 to carry out Above Water Inspections on the TP's of the below locations, with works expected to last for 28 days.

B04,B05,B06,B07,C01,C02,C03,D05,D06,D07,D08,E01,E02,E03,F05,F06,F07,G01,G02,H05,H06,H07,J01,J02,J03,J05,J06,K01,K02,K04,K05,K06,K07,L01,L02,L05,L06 L07,M01,M02,M03,M05,M06,N01,R01,P01

	General Information	Vessel Picture
Name	MCS Blue Norther	
Flag	UK	
Year Built		
MMSI	235096374	
Call Sign	2GDD5	- L
	Vessel Contact Details	
Bridge	07876861745	I I I I I I I I I I I I I I I I I I I
Party Chief		MCS BLUE NORTHER
Email	mcsbluenorther@maritimecraft.co.uk	Vessel



5 Westermost Rough – Notice to Mariners

5.1 Lighting and Marking Status

A01 fog signal is constantly sounding, the issue is being investigated and awaiting parts. NTM will be updated when the problem has been fixed.

5.2 Other Operations

5.1.1 Blade LEP campaign

The CTV's Kitty Petra and Tia Elizabeth will be on site to conduct the blade repairs until the end of September.

When the technicians are deployed via the ropes an exclusion zone of 100m will be required. All 35 turbines will be visited.

Vessel Information

	General Information	Vessel Picture
Name	Kitty Petra	
Flag	United Kingdom [GB]	The state of the s
Year Built	2013	
MMSI	235103572	
Call Sign	2HGW7	
	Vessel Contact Details	
Bridge		
Party Chief		CHITYPETRA
Email	kittypetra @tidal-transit.com	Vessel

	General Information	Vessel Picture
Name	Tia Elizabeth	
Flag	United Kingdom (GB)	
Year Built	2013	The second secon
MMSI	235098384	
Call Sign	2GLJ2	
	Vessel Contact Details	
Bridge	+44 7497603183	
Party Chief		
Email	tiaelizabeth@tidal-transit.com	Stroot Foy Narine traffloscom



5.1.2 Below water Inspections

Delayed until October. The HBC Achiever will be on site to conduct diving and ROV operations at the locations identified below. The vessel will require a 500m exclusion zone whilst divers and the ROV are deployed.

Vessel information

Name	HBC Achiever	
Flag	Denmark (DK)	
Year Built	2014	
MMSI Numbe	r219305000	
Call Sign	OWMH2	
	Vessel Contact Details	
Bridge	07444612495 (EU) 07533793622 (UK)	OWNEZ CONTROL OF THE PROPERTY
Party Chief		one abilities
Email	achieverbridge@hbc-tec.dk	

MAINIDE A DA A	TUDDINEID	WGS84 (Deg, decimal Minutes)		
WINDFARM	TURBINEID	LONGITUDE	LATITUDE	
WMR01	A04	000° 06.85818950' E	53° 47.47696658' N	
WMR01	D07	000° 07.90033622' E	53° 49.78462890' N	
WMR01	E06	000° 09.25156373' E	53° 49.72492298' N	
WMR01	F01	000° 12.61599900' E	53° 47.99516287' N	
WMR01	F03	000° 11.60091884' E	53° 48.83725758' N	
WMR01	F05	000° 10.57587435' E	53° 49.68731194' N	
WMR01	F07	000° 09.60859260' E	53° 50.49184716' N	



6 Lincs – Notice to Mariners

6.1 Lighting and Marking Status

The lighting and/ or navigational warning systems are currently operational. No planned outages.

6.2 Other Operations

6.2.1 LS62 Generator Replacement

Emergent works will be required at on Lincs Offshore Windfarm for Generator Replacements expected to start around the 20th of September, with works lasting up to a week. There will be the requirement for a 500m Safety Zone for the duration of the operation.

	General Information	Vessel Picture		
Name	Wind			
Flag	Denmark			
Year Built	2011			
MMSI	220520000	1. j.,		
Call Sign	OXSW2	The state of the s		
	Vessel Contact Details	BW # 7		
Bridge	+45 20 48 55 86	2700		
		A CANADA TO THE TAXABLE TO THE TAXAB		
Party Chief				
Email	Master.wind@ziton.eu			







7 Gunfleet Sands – Notice to Mariners

7.1 Lighting and Marking Status

The lighting and/ or navigational warning systems are currently operational. No planned outages.

7.2 Other Operations

None planned

7.3 Cable exposure

There are subsea cables currently exposed as shown on the below chart and coordinates.

ID	Array Cable		Start Coordinate		End Coordinate	
	ID	(m)	X	Y	X	Y
GFS_MBES_T0 01- Unidentified Other	F08-F09	13.4	381926.6813	5734099.2514	381941.1213	5734102.2491
GFS_MBES_T0 02-Cable Exposure	F08-F09	790.93	381230.1477	5733680.7421	381918.2586	5734094.8699
GFS_MBES_T0 03-Cable Exposure	F07-F08	533.19	380968.1396	5733528.5434	381159.7110	5733644.3273
GFS_MBES_T0 04-Cable Exposure	F06-F07	25.25	380380.6553	5733175.2259	380399.7014	5733187.5362



8 Hornsea One – Notice to Mariners

8.1 Lighting and Marking Status

A04 marine lanterns & foghorn are currently inoperative. There are no other planned outages.

8.2 Other Operations

8.2.1 Drone Blade Inspections

On the 25th August, the vessel Ary will be on site to complete Blade Inspections via drone. All 174 WTG's will be inspected. We anticipate the work will take around 30 days to complete. Works ongoing.

Vessel Information

General Information		Vessel Picture
Name	Ary	To the second se
Flag	VANUATU	
Year Built	1980	, to 1
MMSI	577031000	
Call Sign	YJQJ5	HI I MANUAL TO A STATE OF THE PARTY OF THE P
Vessel Contact Details		THE PLANT OF THE PARTY OF THE P
Bridge		ARY
Party Chief		
Email		