## KING'S LYNN CONSERVANCY BOARD.

Notice to Mariners No. 19 / 2023



## East Coast of England - The Wash

## Approaches to Wisbech

## Wisbech Anchorage,"W2" lightbuoy missing

Mariners are advised that W2 light buoy (52° 54'.942N 000°16'.003E) has been reported as missing from station.

A replacement buoy will be established in due course.

Please contact the Harbour Office for further information.

16<sup>th</sup> August 2023

P M Bailey Deputy Harbour Master. Harbour Office, King's Lynn, Norfolk PE30 ILL T: 01553 773411 www.kingslynnport.co.uk