

KING'S LYNN CONSERVANCY BOARD.



Notice to Mariners No. 20 / 2023

East Coast of England - The Wash

Approaches to Kings Lynn

Collapse of Beacon B

Mariners are advised that Beacon B (52° 49'.090N 000°21'.136E) has been severely damaged following collision by a fishing boat and is currently unlit.

The area to the West of above position is to be considered as foul ground.

Works to remove the beacon and establishment of a temporary buoy or beacon will be progressed and further NtMs will be issued as required.

Please contact the Harbour Office for further information.

17th August 2023

P M Bailey
Deputy Harbour Master.
Harbour Office,
King's Lynn,
Norfolk PE30 ILL
T: 01553 773411
www.kingslynnport.co.uk